## Take the Kink Out of your Hose





Take a look behind your dryer. Chances are the back of it is about five or six inches away from the wall and the vent hose resembles a snake. These tight bends in the

exhaust hose can accelerate lint accumulation, which in turn reduces the dryer's efficiency and poses a possible fire hazard. The Dryerbox from In-O-Vate Technologies offers a remarkably simple, inexpensive and effective solution. The metal receptacle installs between wall studs (there are a few different styles tailored for new construction or retrofit as well as varying stud sizes) and makes the dryer/vent connection safe and efficient. The company states that lint buildup is reduced with the unencumbered vent and clothes will dry faster, which could save users a few energy dollars every year. It also allows the back of the dryer to be placed against the wall, resulting in about one square foot of additional space in the front. Call 888-443-7937 or visit www.dryerbox.com for pricing and ordering information.